

Urano

Modello/Model	Watt	Alimentazione/Input
URANO2001	0,4W	12Vdc
URANO2002	0,6W	12Vdc
URANO2003	0,6W	12Vdc
URANO2012	0,5W	12Vdc

IT

ISTRUZIONI DI SICUREZZA


- L'apparecchio deve essere installato, connesso e testato da un elettricista qualificato e in accordo con le norme vigenti.
- Disconnettere l'alimentatore prima dell'installazione o della manutenzione dell'apparecchio e assicurarsi che i cavi non vengano danneggiati.
- Pulire l'apparecchio con un panno leggero e un detergente a pH neutro.
- Laddove si abusasse dell'apparecchio o si apportassero modifiche, la garanzia sarebbe da considerarsi nulla.
- Il fornitore è libero di apportare modifiche al design, specificazioni ed istruzioni di montaggio.

EN

SAFETY INSTRUCTIONS

- The device should be installed, connected and tested by a qualified electrician, and in accordance with local regulations.
- Turn off the power supply before installation or maintenance of the device, and make sure that the cables will not be squeezed or damaged by sharp edges.
- Clean the device with a soft cloth and a standard pH neutral detergent. Stainless steel surfaces should be maintained regularly.
- Misuse or changes to the device cause loss of warranty.
- The manufacturer is free to change the design, specifications and instructions for assembly.

ISTRUZIONI PER L'INSTALLAZIONE/INSTALLATION INSTRUCTIONS



1

IT Realizzare il foro nella parete.

EN Make, in the wall, the hole for the light fitting.

2

IT Gli apparecchi, per sicurezza nei confronti del grado di protezione, sono sigillati e forniti di cavo di alimentazione. Realizzare la connessione elettrica semplicemente collegando il cavo all'alimentatore senza aprire nè manomettere l'apparecchio, poi fissate l'apparecchio a parete.


EN The devices, in order to grant the IP rate, are delivered sealed and equipped with power supply cable. Connect the device to the plant simply linking the supply cable to the driver, without opening or tamper with the device. Then install the device to wall.

3


IT Verificare la corretta esecuzione dei collegamenti al circuito di alimentazione, procedere con l'accensione.

EN After verifying the correct circuit, wiring to the power supply, switch on the electricity for the light fitting.


URANO2001



URANO2002



URANO2003



URANO2012

